

What is Washington's proposed solution?

- Add PO_4^{3-} to increase the pH of the water to 9, pushing the water into the zone in the stability field diagram where $\text{Pb}_3(\text{CO}_3)_2(\text{OH})_2$ [solid] will form.
- But this may have serious side effects, including growing brass corrosion.....

